




Kondenssaattorit:

C 1.	50	cm.	C 11.	0,1	MF.
C 2.	100	"	C 12.	25	"
C 3.	150	"	C 13.	16	"
C 4.	500	"	C 14.	880,7	PF.
C 5.	2000	"	C 15.	1517	"
C 6.	2000/2000v.	"	C 16.	250	"
C 7.	5000/2000v.	"			
C 8.	10000	"			
C 9.	18000	"			
C 10.	20000	MF.			

Vastukset:

R 1.	50	Ω	R 11.	125	K Ω
R 2.	100	"	R 12.	200	"
R 3.	500	"	R 13.	500	"
R 4.	2,5	K Ω	R 14.	1	M Ω
R 5.	5	"	R 15.	2	"
R 6.	10	"	R 16.	460	Ω
R 7.	25	"	R 17.	320	"
R 8.	50	"	R 18.	150	"
R 9.	80	"	R 19.	50	"
R 10.	100	"			

ASA 417 v.