



Kond.	mm	mm	mm
C 1	50	oh	1
C 2	100	"	1
C 3	150	"	1
C 4	3000	"	1
C 5	10000	"	1
C 6	0,1	MF	1
C 7	2	"	1
C 8	25	"	1

Vastukset.	R 1	R 2	R 3	R 4	R 5	R 6	R 7
R 1	2,5 Kohm	100	200	300	1 Mohm	50 Kohm	300 + 150 ohm
R 2	"	"	"	"	"	"	ord.
R 3	"	"	"	"	"	"	
R 4	"	"	"	"	"	"	
R 5	"	"	"	"	"	"	
R 6	"	"	"	"	"	"	
R 7	"	"	"	"	"	"	





Kond.	mm	kap.
C1	50 om	1
C2	100 "	1
C3	150 "	1
C4	3000 "	1
C5	10000 "	1
C6	0,1 MF	3
C7	2 "	1
C8	25 "	1

Vaestukset.	kap.
R1 2,5 Kohm	1
R2 100 "	2
R3 200 "	1
R4 500 "	1
R5 1 Mohm	1
R6 50 Kohm	1
R7 300 + 150 ohm kord.	1

