



ASA, 516 P.

Kondensaattorit:

C 1	25 cm	4	kpl.
C 2	50 "	1	"
C 3	100 "	5	"
C 4	3000 "	1	"
C 5	5000 "	1	"
C 6	10000 "	2	"
C 7	18000 "	2	"
C 8	20000 "	2	"
C 9	0,1 MF	3	"
C10	0,5 "	1	"
C11	2 "	1	"
C12	25 "	2	"
C13	150 PF	4	"
C14	1415 "	1	"
C15	1587 "	1	"

Västukset:

R 1	1 Kohm	1	kpl.
R 2	8,5 "	1	"
R 3	10 "	1	"
R 4	50 "	1	"
R 5	64 "	1	"
R 6	100 "	4	"
R 7	200 "	2	"
R 8	300 "	2	"
R 9	500 "	2	"
R10	1 Mohm	3	"
R11	1,5 "	1	"
R12	50 Kohm	1	"
R13	500 "	1	"
R14	300 + 700 Ohm Sirutor	1	"

A S A 516 P.